


Aceon

Bright Inc

2017
CATALOG
ENGINE
COOLANT
TEMPERATURE
SENSORS



**SAME QUALITY
DIFFERENT BOX**



**Engine Coolant
Temperature
Sensors**

(626) 624-9000 www.aceonbright.com sales@usaceon.com

ACEON #	WELLS#	ACDELCO #	PICTURE	MORE INTERCHANGES	YEAR	MAKE	MORE MAKE
8822-1202	SU112	213-1103, 213-4509, 213-4514, 213-953		SU112,213-1103, 213-4509, 213-4514,213-953, 5S1475,WT3018, WT5132, 71-2509, TS10005,TS10076, TS10092,TS148,TS4017, TS5732, TS7263, 12191170, 12608814, 15326388,15369305, 25036898, 25037062,96181508, 96182634, 8-12191-170-0, 8-15369-305-0, 8-15404-280-0, 12191170, 25036898, 25037062, 96182634, TS-617, TX16, TX89,211-1011	1988-2014	Chevrolet	GM
8822-3501	SU3003	211-1032		SU3003, 5S1506, WT5013,71-2553, TS10038,TS5503, 36569,MD149338, TX74, 211-1032	1983-1996	Dodge	Mitsubishi
8822-2102	SU306	213-4182		SU306, 213-4182, 5S1505, WT3005, 71-2552,TS10062, TS5552,36425,1 2351978, 39220-21310, 39220-21320, 39220-21330,MD069879, TX32, 211-1010	1985-2001	Hyundai	Mitsubishi Dodge
8822-3201	SU4006	213-1082		SU4006, 213-1082, 5S1468,158-0154, WT5009,71-2500, TS10180,TS5553, 37870-PJ7-003, 5-86202-847-0, 36426, TX37, 211-1015	1988-2006	Honda	Acura
8822-3101	SU405			SU405, 213-394,213-61, 5S1492,11911111000,158-0134, 201-1676,WT5000,71-2535, TS10042,TS10181,TS10199, TS5520, E8GY-10884-B, E8GY-12A648-A,F3XY-10884-A, F3XY-10884-B,12351989, 94845472,96056758,94845472, 96056758,8574-18-840, SWE2089A,22630-51E00, 22630-51E02,22630-51E10, 22630-V5010,TX18, 13650-84101,89422-12010, 89422-30020,89422-87701, 211-1019	1975-1994	Various Vehicles	
8822-3301	SU4072	213- 1083,213-746		SU4072, 213-1083, 213-746, 5S1522, WT3071, 71-2572, TS10064,TS10145, 2-21019, TS5583, F6XA-10884-AA, F6XZ-10884-AA, SW5150, 22630-0M200, 22630-44B10, 22630-44B20,22630-71L00, 22630-7Y000,TX78, 211-1031	1993-2012	Nissan	Infiniti

ACEON #	WELLS#	ACDELCO #	PICTURE	MORE INTERCHANGES	YEAR	MAKE	MORE MAKE
8822-6102	SU4122			SU405, 213-394,213-61, 5S1492, 11911111000,158-0134, 201-1676, WT5000, 71-2535, TS10042, TS10181, TS10199, TS5520, E8GY-10884-B, E8GY-12A648-A, F3XY-10884-A, F3XY-10884-B, 12351989, 94845472, 96056758, 94845472, 96056758, 8574-18-840, SWE2089A, 22630-51E00, 22630-51E02, 22630-51E10, 22630, V5010, TX18, 13650-84101, 89422-12010, 89422-30020, 89422-87701, 211-1019	1975-1994	Various Vehicles	
8822-6201	SU4122			SU405, 213-394,213-61, 5S1492, 11911111000,158-0134, 201-1676, WT5000, 71-2535, TS10042, TS10181, TS10199, TS5520, E8GY-10884-B, E8GY-12A648-A, F3XY-10884-A, F3XY-10884-B, 12351989, 94845472, 96056758, 94845472, 96056758, 8574-18-840, SWE2089A, 22630-51E00, 22630-51E02, 22630-51E10, 22630, V5010, TX18, 13650-84101, 89422-12010, 89422-30020, 89422-87701, 211-1019	1975-1994	Various Vehicles	
8822-2103	SU4123			SU4123, 5S1532, WT5013, 71-2583, TS10144, TS5503, 39220-26300, 39220-35510, 39220-35520, TX74	1995-1998	Hyundai	
8822-2201	SU4261			SU4261, 5S1543, WT5000, 71-2595, OK011-18-840, K8574-18-840, K8574-18-840, TX18	1994-1997	Kia	
8822-6501	SU4336	213-1086		SU4336, 213-1086, 5S1476, 201-1713, WT632, 71-2510, TS10129, TS6112, TS-360, 025906041A	1990-2001	Volkswagen	Audi
8822-6502	SU5404			802 54024 500, 5S1608, TS-477, 1802-18931, SU5404 5S1478, WT5129, SU6453, TS10236, 8365, TS477, TS477T, 140-834, SU5404	1996-2008	Volkswagen	Audi

ACEON #	WELLS#	ACDELCO #	PICTURE	MORE INTERCHANGES	YEAR	MAKE	MORE MAKE
8822-2101	SU5541	213-4506		213-4506, 5S1533, 158-0623, WT5135, 71-2584, TS5734, 39220-38020, SU5541	2000-2011	Hyundai	Kia
8822-3204	SU5584			SU5584, 5S1529, WT5068, 71-2580, TS10153, TS5618, 37870-PLC-004, TX97	2001-2010	Honda	Acura
8822-6101	SU6053			SU6053, 802 33003 244, WT7253, 014 810 0006, TU414, 71-2609, 000 542 62 18, TS-604, 1802-307528	1997-2009	Mercedes Benz	
8822-6503	SU6453			TS7256, 06A 919 501, TS608, 1802-236629, 71-2672, TS-608, WT5129, SU6453, 1802-18931, 8384, 5S1608	2001-2015	Volkswagen	Audi
8822-6103	SU7685	213-4505		SU7685, 213-4505, 5S6174, WT3072, 71-2699, TS5584, 006 545 45 24, TX121	1986-1993	Mercedes Benz	
8822-6504	TS377			TS377, TS 377, TS-377	1993-2008	Volkswagen	